

UNCLASSIFIED: Distribution A. Approved for public release



TECHNOLOGY DRIVEN. WARFIGHTER FOCUSED.

Eric O'Brien RDECOM - TARDEC TWVS ATO Ground Systems Survivability

maintaining the data needed, and including suggestions for reducing	completing and reviewing the colle g this burden, to Washington Heado ould be aware that notwithstanding	ction of information. Send comme quarters Services, Directorate for I	ents regarding this burden estin information Operations and Re	nate or any other aspect ports, 1215 Jefferson Da	existing data sources, gathering and of this collection of information, avis Highway, Suite 1204, Arlington with a collection of information if it	
		2. REPORT TYPE			3. DATES COVERED	
19 AUG 2010		N/A		-		
4. TITLE AND SUBTITLE			5a. CONTRACT NUMBER			
Characterization Of The Effects Of Armor Weight Cab And Do Structure Of Medium Tactical Vehicles				5b. GRANT NUMBER		
				5c. PROGRAM ELEMENT NUMBER		
6. AUTHOR(S) Eric O'Brien				5d. PROJECT NUMBER		
				5e. TASK NUMBER		
				5f. WORK UNIT NUMBER		
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) US Army RDECOM-TARDEC 6501 E 11 Mile Rd Warren, MI 48397-5000, USA				8. PERFORMING ORGANIZATION REPORT NUMBER 21076		
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)				10. SPONSOR/MONITOR'S ACRONYM(S) TACOM/TARDEC		
				11. SPONSOR/MONITOR'S REPORT NUMBER(S) 21076		
12. DISTRIBUTION/AVAI Approved for pub	LABILITY STATEMENT lic release, distribut	tion unlimited				
13. SUPPLEMENTARY NO The original docum	OTES ment contains color	images.				
14. ABSTRACT						
15. SUBJECT TERMS						
16. SECURITY CLASSIFICATION OF:			17. LIMITATION	18. NUMBER	19a. NAME OF	
a. REPORT	b. ABSTRACT	c. THIS PAGE	OF ABSTRACT SAR	OF PAGES 17	RESPONSIBLE PERSON	
unclassified	unclassified	unclassified				

Report Documentation Page

Form Approved OMB No. 0704-0188





Door Sag Study Background

Part of the Tactical Wheeled Vehicle Survivability Army Technology Objective (TWVS ATO) involves the integration of B-kit and C-kit armor onto the existing M1083 A1P2 Medium Tactical Vehicle (MTV). During the TWVS ATO program, it was noted that the additional weight of the armor kits caused a noticeable drop or sag in the vehicle doors, which prohibited the doors from closing.

In an attempt to better understand the effects of the weight on the MTV cab and door, Finite Element Analysis (FEA) was performed both by the vehicle supplier and TARDEC CASSI. There were discrepancies between the two results of the FEA modeling and neither predicted the actual door sag. Therefore, it was determined that more information was needed in order to better quantify the phenomenon and identify areas for cab reinforcement.

Door Sag Study Objectives

- Quantify the sag that the door of the MTV experienced due to the added weight of the B-Kit and C-Kit
- Determine areas of the door or cab that contributed the most to the sag
- Recommend a path forward





Study Methodology


- Spots on the cab were selected and labeled for strain and 3D measurement
- For door opening angles of 0, 10, 40, and 70 degrees, strain was measured on the cab using Rosette strain gauges and 3D measurements were taken using a probe arm measuring device
- A production metallic 6061 B-kit was placed on the door of cab and measurements were taken again for each door angle
- A surrogate C-kit was created by TARDEC/CGVDI for this study and was meant to closely approximate the actual C-kit weight and center of gravity. The surrogate C-kit was placed on the door of the cab and measurements were taken again.
- The cab was shaken on the Load Handling Simulator in TARDEC CASSI, then measurements were repeated with both the B-kit and C-kit still attached to the cab
- The B-kit and C-kit armor was taken off, and final measurements were taken
- Strain data was analyzed by TARDEC CASSI and 3D data was analyzed by CGVDI and TWVS ATO.




Strain Gauge Results



FEA vs Measured Values - Strain





CASSI's FEA was similar to the vehicle supplier's

From the two models, locations for strain gauges were selected

Maximum Stress = 332 MPa


Safety Factor = 2.1




Strain Gauge Placement



Top Hinge



Bottom Hinge




Not Shown – Gauge #11 on the inside of the B-Pillar (roughly behind Gauge #1)





Measured Peak Strain: A-Cab




- = 700-950 uE
- = 450-700 uE
- = 200-450 uE
- = 0-200 uE
 - 1. Near top left corner of top hinge
 - 2. Near top right corner of top hinge
 - 3. Near bottom left corner of top hinge
 - 4. Near top left corner of bottom hinge
 - 5. Near top right corner of bottom hinge
 - 6. Near bottom left corner of bottom hinge
 - 7. Near bottom right corner of bottom hinge
 - 8. Under belt line near hinge side of door
 - 9. On the side of the top hinge
 - 10. On the top of the top hinge
 - 11. Inside of cab, mounted on B-pillar channel





Measured Peak Strain: w/ B-kit




- = 700-950 uE
- = 450-700 uE
- = 200-450 uE
- = 0-200 uE
 - 1. Near top left corner of top hinge
 - 2. Near top right corner of top hinge
 - 3. Near bottom left corner of top hinge
 - 4. Near top left corner of bottom hinge
 - 5. Near top right corner of bottom hinge
 - 6. Near bottom left corner of bottom hinge
 - 7. Near bottom right corner of bottom hinge
 - 8. Under belt line near hinge side of door
 - 9. On the side of the top hinge
 - 10. On the top of the top hinge
 - 11. Inside of cab, mounted on B-pillar channel





Measured Peak Strain: w/ B-kit + C-kit




- = 700-950 uE
- = 450-700 uE
- = 200-450 uE
- = 0-200 uE
- 1. Near top left corner of top hinge
- 2. Near top right corner of top hinge
- 3. Near bottom left corner of top hinge
- 4. Near top left corner of bottom hinge
- 5. Near top right corner of bottom hinge
- 6. Near bottom left corner of bottom hinge
- 7. Near bottom right corner of bottom hinge
- 8. Under belt line near hinge side of door
- 9. On the side of the top hinge
- 10. On the top of the top hinge
- 11. Inside of cab, mounted on B-pillar channel





Measured Peak Strain: Post Shaker w/ B-kit + C-kit




- = 950-3050 uE
- = 700-950 uE
- = 450-700 uE
- = 200-450 uE
- = 0-200 uE
- = Damaged
- 1. Near top left corner of top hinge
- 2. Near top right corner of top hinge
- 3. Near bottom left corner of top hinge
- 4. Near top left corner of bottom hinge
- 5. Near top right corner of bottom hinge
- 6. Near bottom left corner of bottom hinge
- 7. Near bottom right corner of bottom hinge
- 8. Under belt line near hinge side of door
- 9. On the side of the top hinge
- 10. On the top of the top hinge
- 11. Inside of cab, mounted on B-pillar channel





Measured Peak Strain: Post Shaker A-Cab



- = 700-950 uE
- = 450-700 uE
- = 200-450 uE
- = 0-200 uE
- 1. Near top left corner of top hinge
- 2. Near top right corner of top hinge
- 3. Near bottom left corner of top hinge
- 4. Near top left corner of bottom hinge
- 5. Near top right corner of bottom hinge
- 6. Near bottom left corner of bottom hinge
- 7. Near bottom right corner of bottom hinge
- 8. Under belt line near hinge side of door
- 9. On the side of the top hinge
- 10. On the top of the top hinge
- 11. Inside of cab, mounted on B-pillar channel



-2.215E+02


1.845E+02 1.476E+02


1.107E+02 7.382E+01

Strain Gauge Results



FEA vs Measured Values – Strain with both B- and C-kits





Maximum Stress = 332 MPa Safety Factor = 2.1 = 700-950 uE

= 450-700 uE

= 200–450 uE

= 0–200 uE



Probe Arm Results






Probe Arm 3D
Data Collection
Points

A-Pillar

B-Pillar And Hinges





Door And Inside Cab

Reference Points



Tactical Wheeled Vehicle Survivability ATO



Probe Arm Results



Quantify Sag At 10 Degrees Open

- •Top Corner of Door Moved:
 - •0.27 in. Down
 - •0.23 in. Forward
 - •0.28 in. Outboard
- •Latch Moved:
 - •0.32 in. Down





Shaker Test



TARDEC Designed and Fabricated A Fixture To Mount An MTV Cab To The Load Handling Simulator For Shaker Tests.






Shaker Results




After Shaker Test (Aborted After 160 Miles)

Note: Doors were not fully latched, only one combat lock was engaged, and no door assist was included.







Cracks near hinge attachments



Probe Arm Results



Contribution of each measured part to overall sag of the door

- A-Pillar negligible
- B-Pillar 20% (Deflected Outboard)
- Hinges 60% (Top Hinge is Opening Up Slightly and Designed Clearances at Pivot Allow for Movement)
- Door Structure 20% (Deflection at Hinge Attachments and Twisting)



Path Forward



Recommendations:

- Conduct Hinge Layout After All Testing
- Next Generation Hinge Needs To Be Larger With Tighter Tolerances At Pivot Point
- Strengthen B-Pillar and Door Near Hinge Attachment Points
- More Robust/Multiple Striker Strategy (Bank Vault)
- Improve FEA Analysis to Include Hinge and Door Components
- Conduct Similar Studies (FEA and Physical) on Other TWV's